User Manual PSM/PSA Series



Table of content

01	INTRODUCTION		
05	PREPARATION		
	Leveling the balanceConnecting and Switching	on	
06	CALIBRATION		
	©7 Single-point calibration 10 weight value setting	linearity calibration Auto-calibration	internal calibration -
11	SET UP AND OPERATION		
	11 BALANCE SETUP		
	Unit conversion Sensitivity setting Interface Parameters	12 Baud rate setting 15 Filter level setting	3 Time setting Frint setting
	OPERATION		
	18 Simple weighing 21 Density determination 28 Pipette calibration	Piece countingDynamic weighingDual program switching	Percent weighingSummation Function
32	TROUBLESHOOTING		
32	COMPONENTS LIST		

1. INTRODUCTION

PSA/PSM series work on electromagnetic force compensation technology and micro processor which implements high speed stabilization and high reliability. It can be widely used in industry, agriculture, commerce, schools, scientific research and other institutions to quickly weighing the quality and quantity of objects.

Safety Precautions











Avoid direct sunlight

Avoid vibrations


Avoid strong drafts

Avoid temperature fluctuations

^{*}Verify that the AC Adapter input voltage matches the local AC power supply.

^{*}Sufficient spacing for balances: >15cm all around the instrument.

Diagram




1	Terminal	8	USB-B port
2	Front panel draft shield	9	Socket for power adapter
3	Top door draft shield	10	Bubble level
4	Side door draft shield(right/left)	11	Below weighing(optional)
5	Weighing pan	(4)	Press button
6	Leveling feet	9	Put weight or object on the pan
7	RS232 interface	6	Take off the weight or object

Button



Display information



No.	Display	Describe
1	Max:	Modeldisplay
2	ă	Internal calibration sign
3	_	Negative weight value
4	0	Stablevalue
5	Δ <u>Γ</u> Δ	Weighingsign
6		Density determination
7		Piece counting
8	ΔΔ.	Dynamic weighing
9	Σ	Summation
10		Progressbar
11	88:88:88	Time setting
12	W1 W2	W1:weightinair,W2:weightinliquid
13	8	Unauthenticated numbers
14		Unit display

Parameter

PSA Series Analytical Balance

Model	PSA120	PSA220	PSA320	PSA420	PSA520			
Capacity:	120g	220g	320g	420g	520g			
Readability:			0.1m	g				
Linearity:	±0.	2mg		±0.3mg				
Repeatability:	±0.	1mg		±0.2mg				
Calibration:			Interr	nal				
Stability time:	1,	1,5s 2s						
Working Temp:		10-40℃						
Accuracy Class:			CLAS	SI				
Pan size:		Ø90mm						
Output Interface:			RS232 Ser	ial,USB				
Dimensions:		40cm x 22cm x 31cm						
Net Wight:		6280g						
Power Supply		AC110-240V						
	1							


PSM Series Semi Micro Balance

Model	PSM1055 PSM2055		PSM105	PSM125					
Capacity:	100g/51g	100g/51g 220g/51g		120g					
Readability:	0.1mg/	0.01mg	0.01	mg					
Linearity:	±0.2mg/	±0.05mg	±0.0	5mg					
Repeatability:	±0.2mg/	±0.03mg	±0.0	3mg					
Calibration:		Internal							
Stability time:	≤4s								
Working Temp:		10-40℃							
Accuracy Class:		CL	ASS I						
Pan size:		Ø	90mm						
Output Interface:		RS232	Serial,USB						
Dimensions:		40cm x 2	2cm x 31cm						
Net Wight:		6280g							
Power Supply		AC110-240V							

2. PREPARATION

Leveling the Balance

- 1 Put the balance on the stable desk, the desk can not be moved.
- adjust the 2 Leveling Feet on the bottom, until the bubble is centered in the circle, then installing the scale pan:



bubble right above clockwise rotate two leveling feet

bubble right below counterclockwise rotate two leveling feet

bubble left counterclockwise rotate left leveling foot clockwise rotate right leveling foot

bubble right counterclockwise rotate right leveling foot clockwise rotate left leveling foot

Connecting and Switching on

1 Plug in the AC/CD adapter




3 Press ON/OFF button





2 Connect the terminal with the balance



Balance enter the weighing interface

When the operating temperature changed, put the balance in the new place for 2 hours in the state of "power on", to make the balance comply with the new temperature.


Attention: If the number on display is not stable in first boot, this occurred by operating temprature you can press "TARE" botton repeatly and lay aside for 30 minutes

3. CALIBRATION


In order to get accurate weighing result, balance should be calibrated before the below usage scenarios.

- 1 Before first use
- 2 Balance power off for long time or power error.
- 3 After changing the operating environment.
- [4] Perform regularly in weighing procedure.


Chose the calibration methods (follow the sequence)




External calibration(single-point calibration)



Linear Calibration




Internal calibration weight value setting (Intl. calibration balance only)



Weightvaluesetting

If the balance model is an internal calibration model, please directly press the calibration button to calibrate.

Auto-calibration




Remark: Balance should keep "0.0000", Tare the balance if balance not shown "0.0000" when reach 30 minutes.

4. SET UP AND OPERATION


Balance set up






Remark: Other units are customizable


Baud rate setting



Time setting




Sensitivitysetting




REMARK: factory setting sensitivity "-ASD-3-", suitable for most using environment. Higher sensitivity required better environment. Do not adjust the sensitivity without consulting the factory.

Filter level setting



REMARK: filter level is the internal calculating time of balance, factory setting is "-Int-3-", do not change by yourself without professional instruction.

Print setting



TARE

Save settings

Interface Parameters

Rs232 interface

- Connection

Balance (9 pins) PC/Printer (9 pins)
RXD (Input) 2	2
TXD (Output)3	3
GND (Ground) 5	5


- The baudrate by default is 9600 bps (see Baudrate setting)
- Data format: 10 bits, 0 as start bit, 1 as stop bit, 8 digits (ASCII code) No odd and even numbers adjusting
- Data output: by default is continuous mode. The data ouput mode can be changed into press output, timing output and continuous output (see Data output setting)

- Output data format

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Туре	Data	Unit	Unit	Unit	Return	Line								
or					or	or								feed
data					dot	dot								

OPERATION

Simple weighing



Under weighing interface


....

Put object on the scale pan

Max: [2] 9 44 00:00:00


Get object weight

Piece counting




Enter piece counting mode






-COU-10- sample quantity 10PCS





-COU-10- sample quantity 25PCS

→




-COU-10- sample quantity 50PCS




Save settings

Piece counting




Remark: If test the same sample second time, don't need re-sampling.




Remark: If use the same contrast second time, don't need re-sampling.


Density determination (need gravity kit - optional)



Density determination (need gravity kit - optional)




Density determination (need gravity kit - optional)




Remark: Liquid density weighing, need particular density kit, please consult manufacturer of operating instruction.


Dynamic weighing




Summation Function




Summation Function



Summation Function




Pipette calibration




28


Pipette calibration



Pipette calibration



Dual program switching



Remark: when switch to another program, please make a linear calibration again to unlock the balance.

5.TROUBLESHOOTING

Problem	Cause	Solution
No display	No power supply; Fuse damaged; Power transformer is damaged.	Plug in adapter; Change the fuse; Change the power transformer; If problem persists, send the balance to the technical service for repair.
Unstable display	Bad working conditions; Air flow something between the scale pan and working table; The power exceeds its permissible value and is unstable; Static electricity.	Improve the working condition, close the windshield; Remove the pan and clean well the balance surface; Connect the balance to power supply 110-220 V AC; Static elimination.
Poor accuracy	Improper calibration; The weight of the recipient has not been tared; Big temperature difference; The balance is not horizontal.	Make calibration; Make tare; Put into suitable environment; Adjust level of balance.

6.COMPONENTSLIST

Balance	1
Balance pan	1
Adapter	1
Instruction manual	1
Weight(external)	1
(calibration) glove	1